

ICE CREAM DIPPING CABINET



INSTRUCTIONS

STEP 1

- Make sure unit is on a level surface.

STEP 2

- Plug unit into a 110v outlet.

STEP 3

- Close slider doors on unit.

STEP 4

- Unit is pre-set to get to the correct temperature. There is an on/off light switch next to the temp gauge.

STEP 5

- Unit will take approximately 2 hrs. to cool before using.

Trouble shooting:

- If unit is not working correctly unplug unit from outlet and wait 3 to 5 minutes unit will reset it-self then plug unit back in.



EVENT SOURCE
PANACHE EVENTS

consistently delivering™

EVENT SOURCE

EventSource.com
877.901.0000

PANACHE EVENTS

PanacheEvents.com
800.30.PARTY (72789)

AFTER HOURS

Call above toll free numbers and press Option 2. Please leave a message and we will respond shortly.

SKU 304-4050