

ICE CREAM DIPPING CABINET



INSTRUCTIONS

STEP 1

Make sure the unit is on a level surface.

STEP 2

Plug the unit into a 110V outlet.

STEP 3

Close slider doors on unit.

STEP 4

Unit is pre-set to get to the correct temperature. There is an on/off light switch next to the temperature gauge.

STEP 5

Unit will take approximately 2 hours to cool before using.

Troubleshooting:

If the unit is not working correctly, unplug it from the outlet and wait 3-5 minutes. This will allow the unit to reset, and you may plug it in after.

AFTER HOURS:

Contact your local branch.
