POPCORN MACHINE



STEP 1

Turn all switches to the **ON** position.

STEP 2

Allow empty kettle to heat 2-3 minutes.

STEP 3

Insert butter package and allow butter to melt.

STEP 4

Add popcorn kernels and close lid on kettle.

STEP 4

While popping final serving of popcorn - as kernels begin to pop - TURN THE KETTLE HEAT OFF!

One packet of popcorn will serve 10 cones or 30 bags.



consistently deliveringtm

EVENT SOURCE EventSource.com

877.901.0000

PANACHE EVENTS

PanacheEvents.com

800.30.PARTY (72789)

AFTER HOURS

Call above toll free numbers and press Option 2. Please leave a message and we will respond shortly.

SKU 550-500

Machine Scoop Kettle 2 Hinged Doors Cone Holding and Drip Trays

ADDITIONAL OPTIONS

Cart Popcorn Plastic or Paper Bags Paper Cones



WARNING

Do not immerse kettle in water during cleaning!



NOTE

Keep doors open while popping the popcorn.

Pop one bag at a time to avoid burning the kernels.